

Inspection Photos
Location Name: Zschach State 24-2
Location ID: 313240



Photo 1. Picture of Form 21 as filled out and signed in the field.



Inspection Photos
Location Name: Zschach State 24-2
Location ID: 313240



Photo 2. Bradenhead access has been installed. Water present in cellar.



Photo 3. Close up of photo 2.



Inspection Photos
Location Name: Zschach State 24-2
Location ID: 313240



Photo 4. Tank label peeling.



Photo 5. Gauge hatch open on diesel fuel tank.