

Inspection Photos
Location Name: Simpson 23-8
Location ID: 313130



Photo 1. Overview of location taken facing south.



Photo 2. Tank label peeling.

