

Inspection Photos
Location Name: Frosty Acres 1
Location ID: 313195



Photo 1. Overview of location taken facing east.



Inspection Photos
Location Name: Frosty Acres 1
Location ID: 313195



Photo 2. No bradenhead access apparent.



Photo 3. Incomplete tank label.



Inspection Photos
Location Name: Frosty Acres 1
Location ID: 313195



Photo 4. Tank knocked over. Containers without secondary containment.



Photo 5. Noxious weeds on location.