

Inspection Photos
Location Name: Schieck 11-31
Location ID: 312984



Photo 1. Overview of location taken facing northeast.



Photo 2. Pit.



Inspection Photos
Location Name: Schieck 11-31
Location ID: 312984



Photo 3. Gauge hatch open. Animal burrows in berm.



Photo 4. Close up of open gauge hatch.



Inspection Photos
Location Name: Schieck 11-31
Location ID: 312984



Photo 5. Collapse in access road.



Photo 6. Collapse in access road. Hard hat for scale.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Schieck 11-31
Location ID: 312984



Photo 7. Rills in access road.




Photo 8. Rills in access road. Hard hat for scale.

