

**Inspection Photos**  
**Location Name: BE Behrmann 1, 067-05403**  
**Location ID: 214096**



**IMG 01**  
**Location Sign**



**IMG 02**  
**Site Overview**



**Inspection Photos**  
**Location Name: BE Behrmann 1, 067-05403**  
**Location ID: 214096**



**IMG 03**  
**Wellhead with accessible bradenhead**



**IMG 04**  
**Backside of wellhead**



**Inspection Photos**  
**Location Name: BE Behrmann 1, 067-05403**  
**Location ID: 214096**



**IMG 05**  
**Horizontal separator**



**IMG 06**  
**Horizontal separator**





**Inspection Photos**  
**Location Name: BE Behrmann 1, 067-05403**  
**Location ID: 214096**



**IMG 07**  
**Produced water tank**



**IMG 08**  
**Produced water tank sign**



**Inspection Photos**  
**Location Name: BE Behrmann 1, 067-05403**  
**Location ID: 214096**



**IMG 09**  
**Vertical risers and pig station**



**IMG 10**  
**Telemetry**

**Inspection Photos**  
**Location Name: BE Behrmann 1, 067-05403**  
**Location ID: 214096**



**IMG 11**  
**Encroaching weeds**



**IMG 12**  
**2" riser**



**Inspection Photos**  
**Location Name: BE Behrmann 1, 067-05403**  
**Location ID: 214096**



**IMG 13**

**Weeds encroaching on tank berm**