

GMT Exploration Company LLC, Redstone 6-65 24-36 1HN  
039-06703

Inspection #688312626

4/29/2022

BOP Inspection



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

# PATHFINDER

## PRESSURE TESTING

"FROM THE BATTLEFIELD TO THE OIL FIELD"

ATION SERVICES  
STING  
LIC TORQUING  
CCUMILATOR  
/REPAIR

Colorado Oil and Gas Conservation Commission  
39.51061, -104.6179, 6161.4ft, 200°

970-978-4118  
PATHFINDER PRESSURE

04/29/2022 03:22:03 PM



Colorado Oil and Gas Conservation Commission  
39.51039, -104.61805, 6243.4ft, 223°  
04/29/2022 04:23:18 PM



Colorado Oil and Gas Conservation Commission  
39.51076, -104.61815, 6335.3ft, 29°  
04/28/2022 07:39:09 PM