

GMT Exploration Company LLC, Redstone 6-65 24-36 1HN
039-06703

Inspection #688312629

4/28/2022

Surface Cementing Inspection



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



American Cementers
at Ensign 161

Colorado Oil and Gas Conservation Commission
39.51042, -104.61822, 6210.6ft, 189°
04/28/2022 03:04:45 PM



Colorado Oil and Gas Conservation Commission
39.51076, -104.6182, 6220.5ft, 114°
04/28/2022 06:25:09 PM



Surface Pipe

Colorado Oil and Gas Conservation Commission
39.51028, -104.61746, 6194.2ft, 189°
04/28/2022 03:13:54 PM



Cuttings

Colorado Oil and Gas Conservation Commission
39.51094 -104.61771 6217.2ft 206
04/28/2022 03:16:45 PM



No cement
returns

Colorado Oil and Gas Conservation Commission
39.5106, -104.61772, 6204.1ft, 200°
04/28/2022 05:35:11 PM



No cement
returns at cellar

Colorado Oil and Gas Conservation Commission
39.51055, -104.61797, 6220.5ft, 47°
04/28/2022 08:29:42 PM



Colorado Oil and Gas Conservation Commission
39.51104, -104.61813, 6246.7ft, 194°
04/28/2022 05:59:29 PM



Monitoring
equipment on rig

Colorado Oil and Gas Conservation Commission
39.51074, -104.61814, 6230.3ft, 147°
04/28/2022 06:31:26 PM