

Inspection Photos

API: 073-06568

Operator: JWC OPERATING LLC

Inspection Date: 5/17/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06568 | Date: 5/17/2022

Inspection Photos



Photo 2. Facing toward the TA well site.



Inspection Photos



Photo 3. There is a bucket that has leaked out an oily waste. Bucket and stained soils need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06568 | Date: 5/17/2022

Inspection Photos



Photo 4. There is misc. supplies that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06568 | Date: 5/17/2022