

Inspection Photos

May 13, 2022

Operator: Argali Exploration Company - #3975

Location ID: 312974

Location Name: N.E. Craig State-68N90W /27SENE

Inspection Document #: 702800219

Moffat County, CO

SENE Section 27 T8N R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: N.E. Craig State-68N90W /27SENE

Location ID: 312974



Photo 1. Photo taken from the south of the Location shows an overview of the Location. Photo also shows southern interim areas of the Location are dominated by perennial grasses. Note, GPS coordinates are incorrect due to phone GPS malfunction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800219

Inspection Photos
Location Name: N.E. Craig State-68N90W /27SENE
Location ID: 312974



Photo 2. Photo taken from the interim area at the center of the Location shows the area is dominated by perennial grasses. Photo also shows Canada thistle, a CO List B Noxious weed.



Photo 3. Photo taken from the northeast of the Location shows interim areas dominated by perennial grasses.



Inspection Photos
Location Name: N.E. Craig State-68N90W /27SENE
Location ID: 312974



Photo 4. Photo taken from the wellhead shows water and gas bubbling up through a pipe.

