

# Inspection Photos

May 13, 2022

Operator: Kaiser-Francis Oil Company - #45898

Location ID: 312777

Location Name: Gooch-68N90W /33NESW

Inspection Document #: 702800221

Moffat County, CO

NESW Section 33 T8N R90W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Gooch-68N90W /33NESW  
Location ID: 312777



5/13/22  
+40.624682,-107.469238  
135° SE

**Photo 1.** Photo taken from the west of the Location shows an overview of the Location. Photo also shows interim areas of the Location are dominated by perennial grasses with patches of bare ground. Note, GPS coordinates are incorrect due to phone GPS malfunction.





Inspection Photos  
Location Name: Gooch-68N90W /33NESW  
Location ID: 312777



**Photo 2.** Photo taken from the west of the Location shows interim areas dominated by perennial grasses



**Photo 3.** Photo taken from the northeast of the Location shows interim areas dominated by perennial grasses.