

TEP  
KP 32-9  
Location # 435118



location



location

TEP  
KP 32-9  
Location # 435118



location



location



TEP  
KP 32-9  
Location # 435118



**Access road inlet culvert is cleaned out from previous inspection**



**Opposite side of access road culvert inlet. Sediment discarded on vegetation.**





**TEP**  
**KP 32-9**  
**Location # 435118**



**Previous inspection of culvert inlet on access road**





TEP  
KP 32-9  
Location # 435118



**Random debris**



**Random debris**





TEP  
KP 32-9  
Location # 435118



**Valves missing caps/plugs**



**Valves missing caps/plugs**





TEP  
KP 32-9  
Location # 435118



**Valves missing caps/plugs**



**Cut slope**



TEP  
KP 32-9  
Location # 435118



**Inlet of culvert on location**



**Outlet of culvert on location**