

Inspection Photos  
Operator: Simcoe  
API: 067-08718  
Date: 5/18/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing largely in a grazed condition. Livestock feeding equipment observed in the western project area.





Photo 3. View of the reference area comprised of irrigated grass field.