

Inspection Photos
Operator: Simcoe
API: 067-08910
Date: 5/18/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with western wheatgrass and crested wheatgrass.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of the reference area comprised of sagebrush shrubland with native and introduced grasses in the understory such as western wheatgrass and crested wheatgrass.