

FORM
43Rev
05/21

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

12/03/2021

Document Number:

402886451

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 10705 Contact Person: Mackenzie Smith
Company Name: EVERGREEN NATURAL RESOURCES LLC Phone: (303) 2848820
Address: 1875 LAWRENCE ST STE 1150 Fax: ()
City: DENVER State: CO Zip: 80202 Email: mackenzie.smith@enrllc.com

Identification Information

API Number: 05 - - OGCC Facility ID: 262421 Initial Form 19 or 27 Document number:
Facility Name: PONY EXPRESS Facility Number: 44-31 Facility Type: PIT
Location QtrQtr: SESE Section: 31 Township: 32S Range: 66W Meridian: 6
County: LAS ANIMAS Field Name: PURGATOIRE RIVER
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: EVERGREEN NATURAL RESOURCES LLC Agent Name: Mackenzie Smith Title: Production Engineer
Phone Number: 303-2848820 Email: mackenzie.smith@enrllc.com

Rule 909.J Inspection Information

Date the Pit was Inspected 05/19/2021
On inspection the Pit was: ☒ Unlined ☐ Lined ☐ Fenced ☐ Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 260770 Facility Name: PONY EXPRESS 44-31 Facility Type: Oil and Gas Well
Location: QtrQtr: SESE Sec: 31 Twp: 32S Range: 66W Meridian: 6
County Name: LAS ANIMAS Latitude: 37.208990 Longitude: -104.814630

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 93373 Document Name: edd1 File Name: 260770 - EDD1 10132021.xlsx
SampleType: Matrix:
Facility ID: 260770 Sample ID: 630194 Sample Name: Pony Express 44-31 Sample Date: 09/22/2021
Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: TestAmerica Inc. Lab Sample ID: 280-153283-2

Batch ID: 93374	Document Name: edd2	File Name: 260770 - EDD2 1182021.xlsx	
SampleType: _____		Matrix: _____	
Facility ID: 260770	Sample ID: 630195	Sample Name: Pony Express 44-31	Sample Date: 09/22/2021
Collection Point: WellHead	Matrix: WATER	Pre Post: Rule 909.j initial sample	
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: TestAmerica Inc.	Lab Sample ID: 280-153283-2

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
260770	402886452	260770 - report1 10132021.pdf	Analytical Laboratory Report	PDF
260770	402886453	260770 - Report2 1182021.pdf	Analytical Laboratory Report	PDF

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	05/19/2022

Total: 1 comment(s)