

Inspection Photos  
Location Name: Ewerts 3-18  
Location ID: 305702



Photo 1 WH sign.

Photo 2 WH.

Inspection Photos  
Location Name: Ewerts 3-18  
Location ID: 305702



Photo 3 Braden head combustion device .

Photo 4 TB signs.

**Inspection Photos**  
**Location Name: Ewerts 3-18**  
**Location ID: 305702**



**Photo 5 TB.**

**Photo 6 ECD.**

**Inspection Photos**  
**Location Name: Ewerts 3-18**  
**Location ID: 305702**



**Photo 7 Gas Meter Run, Card indicates current calibration.**

**Photo 8 HHS.**

Inspection Photos  
Location Name: Ewerts 3-18  
Location ID: 305702



Photo 9 Gas Meter Run, Card indicates current calibration.