

# Inspection Photos

May 13, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 425554

Location Name: Kline /21-23

Inspection Document #: 702800227

Moffat County, CO

NENW Section 23 T7N R91W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Kline /21-23  
Location ID: 425554



**Photo 1.** Photo taken from the Location entrance shows signage with incorrect Operator information. The Location cut and fill slopes can be seen in the background.



**Photo 2.** Photo taken from the Location access road which needs to be reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800227



Inspection Photos  
Location Name: Kline /21-23  
Location ID: 425554



**Photo 3.** Photo taken from the northeast of the Location shows an overview of the constructed pad and cut slope.



**Photo 4.** Photo taken from the center of the Location shows the pad surface.



Inspection Photos  
Location Name: Kline /21-23  
Location ID: 425554



**Photo 5.** Photo taken from the east of the Location shows the pad area and cut slope.



**Photo 6.** Photo taken from the east of the Location shows the cut slope.



Inspection Photos  
Location Name: Kline /21-23  
Location ID: 425554



**Photo 7.** Photo taken from the north of the Location shows Dalmatian toadflax, a CO List B Noxious Weed.



**Photo 8.** Photo taken from the south of the Location shows Russian olive, a CO List B Noxious Weed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800227



Inspection Photos  
Location Name: Kline /21-23  
Location ID: 425554



**Photo 9.** Photo taken from the north of the Location shows rill erosion occurring on the cut slope.



**Photo 10.** Photo taken from the west of the Location shows rill erosion occurring on the bare, unprotected fill slope.