

## Inspection Photos

Location Name: 70 RANCHUSX BB-65N63W /35NENW

Location #: 310232



**Photo #1**

**70 RanchUSX BB 35-03 (05-123-26107) Wellsite**

**Plugged & Abandoned | PA**

**~ 50 yds.**

*prior photo: 2019/04/18*



**Photo #2**

**70 RanchUSX BB 35-03 (05-123-26107) Wellsite**

**Plugged & Abandoned | PA**

**~ 25 yds.**

## Inspection Photos

Location Name: 70 RANCHUSX BB-65N63W /35NENW

Location #: 310232



**Photo #3**

**70 RanchUSX BB 35-03** Battery site

**Abandoned**

**Unused Equipment**  
**Gas meter run, riser**

*prior photo: 2019/04/18*



**Photo #4**

**70 RanchUSX BB 35-03** Battery site

**Abandoned**

**Unused Equipment**  
**Gas meter run, riser**

*prior photo: 2022/01/11*

## Inspection Photos

Location Name: 70 RANCHUSX BB-65N63W /35NENW

Location #: 310232



**Photo #5**

**70 RanchUSX BB 35-03 Battery site**

**Abandoned**

**Unused Equipment**

**Gas meter run, riser**

*prior photo: 2019/04/18*



**Photo #6**

**70 RanchUSX BB 35-03 Battery site**

**Abandoned**

**Unused Equipment**

**Gas meter run removed**

**Riser: Line Active**