

# Inspection Photos

May 17, 2022

Operator: Beeman Oil & Gas LLC - #7125

Location ID: 428856

Location Name: Simoes /22-30

Inspection Document #: 702800238

Moffat County, CO

Lot 10 Section 30 T6N R90W


Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

**Location ID: 428856**



5/17/22  
+40.450766,-107.536484  
146° SE

Inspection Number: 702800238

Inspection Photos  
Location Name: Simoes /22-30  
Location ID: 428856



**Photo 3.** Map shows the Location of a ground nesting bird at the southern edge of the production pad. Implementing BMPs to avoid disturbing the nest advised.



Inspection Photos  
Location Name: Simoes /22-30  
Location ID: 428856



**Photo 4.** Photo taken from the center of the Location shows storage of unused equipment.



**Photo 5.** Photo taken from the cut slope at the northwest of the Location shows Dalmatian toadflax, a CO List B Noxious Weed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800238



Inspection Photos  
Location Name: Simoes /22-30  
Location ID: 428856



**Photo 6.** Photo taken from the cut slope at the west of the Location shows musk thistle and houndstongue, both CO List B Noxious Weeds.



**Photo 7.** Photo taken from the southwest of the Location in the interim area shows an area of poor perennial grass establishment with annual undesirable plant species/weeds and noxious weeds. The forb throughout the foreground is houndstongue.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800238



Inspection Photos  
Location Name: Simoes /22-30  
Location ID: 428856



**Photo 8.** Photo taken from the northeast of the Location shows interim areas dominated by perennial grasses. Photo also shows berms with poor perennial grass establishment and greater density of annual undesirable plant species/weeds and noxious weeds.



**Photo 9.** Photo taken from the east of the Location in the interim area shows interim areas in the middleground dominated by perennial grasses. The foreground shows areas of poor perennial grass establishment and greater density of annual undesirable plant species/weeds and noxious weeds.



Inspection Photos  
Location Name: Simoes /22-30  
Location ID: 428856



**Photo 10.** Photo taken from the cut slope to the west of the Location shows erosion. Pedestals are forming on the slope and undercutting and lateral erosion is resulting in exposed roots and vegetation and soil loss from the area above/to the west of the cut. Photo also shows noxious weeds.



**Photo 11.** Refer to Photo 10 comment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800238