

# Inspection Photos

May 17, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 429513

Location Name: Stoddard /CTB

Inspection Document #: 702800240

Moffat County, CO

Lot 10 Section 30 T6N R90W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Stoddard /CTB  
Location ID: 429513



**Photo 1.** Photo taken from the north shows an overview of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800240

Inspection Photos  
Location Name: Stoddard /CTB  
Location ID: 429513



**Photo 2.** Photo taken from the tank battery shows signage with incorrect Operator information.



**Photo 3.** Photo taken from the tank battery shows signage with incorrect Operator information on tanks.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800240

Inspection Photos  
Location Name: Stoddard /CTB  
Location ID: 429513



**Photo 4.** Photo taken from the west of the Location shows weed debris accumulating around equipment. Photo also shows storage of unnecessary equipment (pipe racks).



**Photo 5.** Photo taken from the interim area to the south of the Location shows musk thistle, a CO List B Noxious Weed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800240

Inspection Photos  
Location Name: Stoddard /CTB  
Location ID: 429513



**Photo 6.** Photo taken from the north of the Location shows the interim area dominated by perennial grasses.



**Photo 7.** Photo taken from the east of the Location shows the interim area dominated by perennial grasses. Areas of poor perennial grass colonization are vegetated with annual undesirable plant species/weeds and noxious weeds. Red circles indicate the noxious weed houndstongue.



Inspection Photos  
Location Name: Stoddard /CTB  
Location ID: 429513



**Photo 8.** Photo taken from the cut at the south of the Location shows the slope well vegetated and stabilized by perennial grasses.



**Photo 9.** Refer to Photo 8 comment.