

Inspection Photos
Location Name: Lost Creek 45
Location ID: 310792



Photo 1 – Tank Battery

Photo 2 – NFPA Label

Inspection Photos
Location Name: Lost Creek 45
Location ID: 310792



Photo 3 – Tank Battery Sign



Photo 4 – Content Label

Inspection Photos
Location Name: Lost Creek 45
Location ID: 310792



Photo 5 – Separator



Photo 6 – Unmarked Deadman Anchor

Inspection Photos
Location Name: Lost Creek 45
Location ID: 310792




Photo 7 – Wellhead

Photo 8 – Unmarked Deadman Anchor