

TEP
RMV 150-22
Location # 335332



location



Lack of stabilization/compaction

TEP
RMV 150-22
Location # 335332



Lack of stabilization/compaction



Lack of stabilization/compaction

TEP
RMV 150-22
Location # 335332



Open rat hole



Open rat hole

TEP
RMV 150-22
Location # 335332



May 23, 2022 at 10:28:22 AM
39.505907,-107.869094 ±4.73m
OGCC

Well head fencing and signage

