

TEP
GV 25-27
Location # 311574



location



location

TEP
GV 25-27
Location # 311574



location



Well heads gate and fence falling down



TEP
GV 25-27
Location # 311574



Missing cap/plug



Lack of stabilization/compaction



TEP
GV 25-27
Location # 311574



Lack of stabilization/compaction



Well head entrance gate



TEP
GV 25-27
Location # 311574



Debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources