

Inspection Photos  
Location Name: Christiansen 2  
Location ID: 332947



Photo 1 WH sign.

Photo 2 WH

Inspection Photos  
Location Name: Christiansen 2  
Location ID: 332947



**Photo 3 Pump Jack.**

**Photo 4 Ancillary equip.**

Inspection Photos  
Location Name: Christiansen 2  
Location ID: 332947



Photo 5 Pump Jack seal is leaking.

Photo 6 Stained concrete due to leaking seal.

Inspection Photos  
Location Name: Christiansen 2  
Location ID: 332947



Photo 7 Stained concrete due to leaking seal.

Photo 8 Pump Jack seal is leaking.

Inspection Photos  
Location Name: Christiansen 2  
Location ID: 332947



Photo 9 Stained concrete due to leaking seal.

Photo 10 Stained concrete due to leaking seal.