

Inspection Photos  
Location Name: Christiansen 1  
Location ID: 336288



Photo 1 WH sign.

Photo 2 Weeds growing around WH

Inspection Photos  
Location Name: Christiansen 1  
Location ID: 336288




Photo 3 PJ.

Photo 4 ancillary equipment

Inspection Photos  
Location Name: Christiansen 1  
Location ID: 336288



Photo 5 TB sign faded.

Photo 6 TB

Inspection Photos  
Location Name: Christiansen 1  
Location ID: 336288



Photo 7 Flow line manifolds.

Photo 8 HHS

Inspection Photos  
Location Name: Christiansen 1  
Location ID: 336288



Photo 9 Gas Meter Run