

Inspection Photos

May 17, 2022

Operator: Jetta Operating Company Inc - #44645

Location ID: 312924

Location Name: Craig-66N90W /7NENW

Inspection Document #: 702800250

Moffat County, CO

NENW Section 7 T6N R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Craig-66N90W /7NENW
Location ID: 312924



Photo 1. Photo taken from the east of the Location shows a pile of gravel being stored on the reclaimed area. Tire tracks are widespread in the area and are impacting revegetation.



Inspection Photos
Location Name: Craig-66N90W /7NENW
Location ID: 312924



Photo 2. Photo taken from the east of the Location shows bare ground, sparse germinating grasses and widespread cover of kochia, an annual weed.



Photo 3. Photo taken from the east of the Location shows heavily compacted soils.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800250

Inspection Photos
Location Name: Craig-66N90W /7NENW
Location ID: 312924



Photo 4. Photo taken from the southeast of the Location shows the difference in soil compaction from Photo 3. Soils at the southeast of the Location are not as compacted. Vegetation is dominated by the annual weed kochia and the CO List C Noxious weeds cheatgrass and bulbous bluegrass.



Photo 5. Photo taken from the southeast of the Location shows the vegetation community is dominated by the annual weed kochia and the CO List C Noxious weeds cheatgrass and bulbous bluegrass.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800250

Inspection Photos
Location Name: Craig-66N90W /7NENW
Location ID: 312924



Photo 6. Photo taken from the west of the Location shows areas of the Location not disturbed by vehicles have good germination and coverage of perennial grass seedlings. This area is still densely colonized by the annual weed kochia.



Photo 7. Photo taken from the west of the Locations shows a close-up of the germinating plant community. Seeded perennial grasses are codominant with the annual weed kochia.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800250

Inspection Photos
Location Name: Craig-66N90W /7NENW
Location ID: 312924



Photo 8. Photo taken from the west of the Location shows germination of perennial grasses as well as patches of the annual weed kochia.



Inspection Photos
Location Name: Craig-66N90W /7NENW
Location ID: 312924



Photo 9. Photo taken from the east of the Location shows the reference area is a perennial graminoid meadow consisting of dense cover of smooth brome and arctic rush. Noxious and annual weeds are absent.

