

Inspection Photos
Location Name: Lost Creek 29
Location ID: 305607




Photo 1 – Wellhead – All Valves appear to be Closed at the time of this Inspection



Photo 2 – Tank Battery

Inspection Photos
Location Name: Lost Creek 29
Location ID: 305607



Photo 3 – Sign at Entrance



Photo 4 – NFPA, Content and Capacity Labels missing



Inspection Photos
Location Name: Lost Creek 29
Location ID: 305607



Photo 5 – Content Label needs updated



Photo 6 – Separator and Gas Meter

Inspection Photos
Location Name: Lost Creek 29
Location ID: 305607



Photo 7 – Unmarked Deadman Anchor




Photo 8 – Unused Tanks

Inspection Photos
Location Name: Lost Creek 29
Location ID: 305607




Photo 9 – Unused Tank and Parts