

Inspection Photos

May 18, 2022

Operator: Peakview Operating Company LLC - #10409

Location ID: 312911

Location Name: Buck Peak State-66N90W /16SWNE

Inspection Document #: 702800261

Moffat County, CO

SWNE Section 16 T6N R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Buck Peak State-66N90W /16SWNE
Location ID: 312911



Photo 1. Photo taken from the north of the Location shows an overview of the Location.



Photo 2. Photo taken from the west of the Location shows interim areas dominated by the perennial grass smooth brome.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800261

Inspection Photos
Location Name: Buck Peak State-66N90W /16SWNE
Location ID: 312911



Photo 3. Photo taken from the east of the Location shows the noxious weed whitetop/hoary cress.



Photo 4. Photo taken from the northeast of the Location shows the noxious weed Dalmatian toadflax.



Inspection Photos

Location Name: Buck Peak State-66N90W /16SWNE

Location ID: 312911



Photo 5. Photo taken from the southwest of the Location shows the noxious weed, houndstongue.



Photo 6. Photo taken from the south of the Location shows a rosette of the noxious weed, musk thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800261