

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298



Photo 1 – Wellhead – Unmarked Riser



Photo 2 – Wellhead Sign



Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298



Photo 3 – Wellhead




Photo 4 – Separator – Unused Stairs

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298




Photo 5 – Unused Equipment in SE Corner



Photo 6 – Unused Separators

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298



Photo 7 – Unused Pipe



Photo 8 – Unused Tank Walks, Stairs and PVC Pipe

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298



Photo 9 – Unused Pipe and Tanks



Photo 10 – Unused Tanks

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298



Photo 11 – Unused Pipe and Tanks



Photo 12 – Unused Pipe, Parts and Separator

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298




Photo 13 – Unused Pipe, Tank, and Stairs



Photo 14 – Tank Battery



Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298



Photo 15 – Tank Battery Signs



Photo 16 – Content Label Missing

