

**Inspection Photos**  
**Location Name: M & M #4, 067-06625**  
**Location ID: 215020**



**IMG 01**  
**Well Sign**



**IMG 02**  
**Pump Jack**

**Inspection Photos**  
**Location Name: M & M #4, 067-06625**  
**Location ID: 215020**



**IMG 03**  
**Trash and Debris**



**IMG 04**  
**Unfilled mouse hole**

**Inspection Photos**  
**Location Name: M & M #4, 067-06625**  
**Location ID: 215020**



**IMG 05**  
**Unfilled Mousehole**



**IMG 06**  
**Electric Prime Mover**

**Inspection Photos**  
**Location Name: M & M #4, 067-06625**  
**Location ID: 215020**



**IMG 07**

**Thread protectors and other trash on site**



**IMG 08**

**Electrical conduit and debris**

**Inspection Photos**  
**Location Name: M & M #4, 067-06625**  
**Location ID: 215020**



**IMG 09**  
**Dirt pile**



**IMG 10**  
**Unpainted rig anchor markers**

**Inspection Photos**  
**Location Name: M & M #4, 067-06625**  
**Location ID: 215020**



**IMG 11**  
**Unpainted rig anchor markers**



**IMG 12**  
**Unused equipment**