

LASSO OIL & GAS LLC
CONTINENTAL 63S100W 17SESW
Location # 315226



Sign is illegible. Sign is hung upside down. Sign was made for another well and has this wells information written over the old information. The Api # is not correct. Well name and legal description is illegible.



No braden head access. Surface casing open to atmosphere

LASSO OIL & GAS LLC
CONTINENTAL 63S100W 17SESW
Location # 315226



Heat equipment disassembled from heated separator. Open access to wildlife.



No battery sign at tank battery. Label doesn't meet Rule 605.h. (missing information). No NFPA sticker, no operator name and no operator contact number.


LASSO OIL & GAS LLC

CONTINENTAL 63S100W 17SESW

Location # 315226



No tank berm.
Dead debris covering location and around equipment and tank.



Meter last calibrated in 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

LASSO OIL & GAS LLC
CONTINENTAL 63S100W 17SESW
Location # 315226



**Dead debris covering location and around
equipment and tank.**