

**Inspection Photos**  
**Operator: Southland Royalty Co.**  
**API: 033-06015**  
**Date: 5/20/2022**



Photo 1. View of the plugged wellhead marker facing westward.



Photo 3. View of access road facing south toward the beginning of the access road (where Jeep is parked). Access road needs to be closed and reclaimed.



Photos 3-5. View of scattered trash and debris observed on and adjacent to the well pad, needs to be removed.



Photo 6. View of the northern portion of the project area, largely in a revegetated condition.



Photo 7. View of the reference area comprised of ponderosa pine woodland with gambel oak, black sage, mules ears, antelope bitterbrush, and sandberg bluegrass in the understory.