

Final Reclamation Inspection

May 19, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 326865

Inspection Document #: 697503952

Weld County, CO

SWSW Section 17 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: OCOMA #C17-13
Location ID: 326865



Photo 1. Photo taken from the location entrance, facing East. Photo illustrates the well remains in TA status and the access road.



Inspection Photos
Location Name: OCOMA #C17-13
Location ID: 326865



Photo 2. Photo taken from the associated tank battery location, facing South. Photo illustrates Operator has removed all equipment and has performed final reclamation activities.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503952

Inspection Photos
Location Name: OCOMA #C17-13
Location ID: 326865



Photo 3. Close up photo taken from the associated tank battery location. Photo illustrates desirable vegetation establishment.



Inspection Photos
Location Name: OCOMA #C17-13
Location ID: 326865



Photo 4. Reference photo taken east of the associated tank battery location, facing Southeast.

