

Inspection Photos
Location Name: Ross 8-60 PAD
Location ID: 478239



Photo 1 – First Point of Intersection of a Public Road and the Rig Access Road

Photo 2 – Change of Direction on Access Road from East to South

Inspection Photos
Location Name: Ross 8-60 PAD
Location ID: 478239



Photo 3 – Change in Direction on Access Road from South to East

Photo 4 – Rig Entrance – Roughly 1.5 miles in from the First Point of Intersection of a Public Road