

Inspection Photos

Location Name: Red Cloud 4N64W1 1-11 Tank Battery
Facility ID: 481853



Photo #1 Location

Photo #1 Production Equipment

Inspection Photos
Location Name: Red Cloud 4N64W1 1-11 Tank Battery
Facility ID: 481853



Photo #3 Gas Meter Runs



Photo #4 Pig Station

Inspection Photos

Location Name: Red Cloud 4N64W1 1-11 Tank Battery

Facility ID: 481853



Photo #5 ECD's



Photo #6 Compressors

Inspection Photos

Location Name: Red Cloud 4N64W1 1-11 Tank Battery

Facility ID: 481853



Photo #7 Tank Battery

Photo #8 Lacts

Inspection Photos

Location Name: Red Cloud 4N64W1 1-11 Tank Battery

Facility ID: 481853



Photo #9 Missing Pit Capacity/ Placard Labels

Photo #10 Unused Tote

Inspection Photos

Location Name: Red Cloud 4N64W1 1-11 Tank Battery

Facility ID: 481853



Photo #11 Missing Netting



Photo #12 Unused Equipment/ Stained soil

Inspection Photos
Location Name: Red Cloud 4N64W1 1-11 Tank Battery
Facility ID: 481853




Photo #13 Inaccurate capacity labels on water tanks

Photo #14 Inaccurate capacity labels on water tanks

Inspection Photos

Location Name: Red Cloud 4N64W1 1-11 Tank Battery

Facility ID: 481853



Photo #15 Inaccurate capacity label

Photo #16 Inaccurate capacity label

Inspection Photos
Location Name: Red Cloud 4N64W1 1-11 Tank Battery
Facility ID: 481853



Photo #17 Inaccurate capacity label

Photo #18 Inaccurate capacity label