

Inspection Photos
Location Name: Pace-Connelly 1
Location ID: 318533



Photo 1 Location.

Photo 2 WH sign

Inspection Photos
Location Name: Pace-Connelly 1 Leak
Location ID: 318533



Photo 3 WH.

**Photo 4 Leak at the WH around the tubing and bradenhead
below the Master Valve**