

Inspection Photos
Location Name: Tom L. Russell 2
Location ID: 318279



Photo 1 WH sign.

Photo 2 WH.

Inspection Photos
Location Name: Tom L. Russell 2
Location ID: 318279



Photo 3 PJ.

Photo 4 Ancillary equip..

Inspection Photos
Location Name: Tom L. Russell 2
Location ID: 318279



Photo 5 TB sign.

Photo 6 TB.

Inspection Photos
Location Name: Tom L. Russell 2
Location ID: 318279



Photo 7 Heater treater.

Photo 8 HHS.

Inspection Photos
Location Name: Tom L. Russell 2
Location ID: 318279



Photo 9 Unused Gas Meter Run.



Photo 10 PW vessel, TO flowlines.