

Inspection Photos
Location Name: Bondad 33-9 14, 067-05423
Location ID: 333535



IMG 01
Well sign



IMG 02
Site overview

Inspection Photos
Location Name: Bondad 33-9 14, 067-05423
Location ID: 333535





IMG 03
Cathodic protector



IMG 04
Domestic tap

Location ID: 333535



Inspection Photos
Location Name: Bondad 33-9 14, 067-05423
Location ID: 333535



IMG 07
Produced water tank sign



IMG 08
Produced water tank with encroaching weeds



Inspection Photos
Location Name: Bondad 33-9 14, 067-05423
Location ID: 333535



IMG 09
Encroaching weeds



IMG 10
Oily residue



Inspection Photos
Location Name: Bondad 33-9 14, 067-05423
Location ID: 333535



IMG 11
Exhaust muffler impacting material



IMG 12
Separator



Inspection Photos
Location Name: Bondad 33-9 14, 067-05423
Location ID: 333535



IMG 13
Wellhead with encroaching weeds