

Inspection Photos

Location Name: Alva Short B 1, 067-07129
Location ID: 333535



IMG 01
Well sign



IMG 02
Site overview 1/2

Inspection Photos
Location Name: Alva Short B 1, 067-07129
Location ID: 333535



IMG 03
Site overview 2/2



IMG 04
Unmarked rig anchor

Inspection Photos
Location Name: Alva Short B 1, 067-07129
Location ID: 333535



IMG 05
Telemetry



IMG 06
Generator lube oil

Inspection Photos
Location Name: Alva Short B 1, 067-07129
Location ID: 333535



IMG 07
Generator lube oil over half full



IMG 08
Weeds encroaching wellhead

Inspection Photos
Location Name: Alva Short B 1, 067-07129
Location ID: 333535



IMG 09
Impacted material around wellhead



IMG 10
Weeds encroaching pump jack

Inspection Photos
Location Name: Alva Short B 1, 067-07129
Location ID: 333535



IMG 11
Dead weeds under muffler exhaust



IMG 12
Produced water tank

Inspection Photos
Location Name: Alva Short B 1, 067-07129
Location ID: 333535



IMG 13

Produced water tank deteriorated and not legible



IMG 14

Produced water tank

Inspection Photos
Location Name: Alva Short B 1, 067-07129
Location ID: 333535



IMG 15
Separator with vent screen



IMG 16
Domestic tap