

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403060086

Date Received:

05/26/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10634

Name of Operator: P O & G OPERATING LLC

Address: 5847 SAN FELIPE SUITE 3200

City: HOUSTON State: TX Zip: 77057

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Charlotte Nash

713-244-0779

regulatory@pogresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 701001001

Inspection Date: 07/20/2020

FIR Submit Date: 07/21/2020

FIR Status: _____

Inspected Operator Information:

Company Name: P O & G OPERATING LLC

Company Number: 10634

Address: 5847 SAN FELIPE SUITE 3200

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 324943

Location Name: BEESON-610S45W Number: 21NWNW County: KIT CARSON

Qtrqr: NWN Sec: 21 Twp: 10S Range: 45W Meridian: 6

Latitude: 39.169830 Longitude: -102.443500

FACILITY - API Number: 05-063-00 Facility ID: 213712

Facility Name: BEESON Number: 4-21

Qtrqr: NWN Sec: 21 Twp: 10S Range: 45W Meridian: 6

Latitude: 39.169830 Longitude: -102.443500

CORRECTIVE ACTIONS:

1 CA# 140758

Corrective Action: Continue with final reclamation process

Date: _____

Response: CA COMPLETED

Date of Completion: 03/01/2022

Operator Comment: Location is ready for reinspection

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: PO&G request re-inspection of the Beeson release from P&A

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Charlotte Nash

Signed: _____

Title: Prod & Regulatory Analyst

Date: 5/26/2022 7:34:14 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403060095	Inspection Report
-----------	-------------------

Total Attach: 1 Files