

**Inspection Photos**  
**Operator: Hilcorp Energy**  
**API: 067-07232**  
**Date: 5/24/2022**



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the eastern project area from the southwestern corner facing northward.



Photo 3. View of area around the well marker where bare soils remain.



Photo 4. View of the northwestern portion of the project area where sparse desirable vegetation observed.



Photo 5. View of reference area vegetation comprised of open grass field with a mix of native and non-native grasses and forbs such as western wheatgrass, purple mustard, and flixweed.