

# Construction and Stormwater Inspection

May 26, 2022

Operator: EXTRACTION OIL & GAS INC- #10459

Location ID: 460670

Inspection Document #: 697503970

Weld County, CO

SWSW Section 18 T2N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Blue Paintbrush /Pad  
Location ID: 460670



**Photo 1.** COGCC drone aerial imagery taken from location, facing Northwest. Photo illustrates the access point off CR 20.5 (red arrow) which is an established oil and gas access road for the Crestone Peak Williams Unit facility. The red box is the approximate access road that will be constructed for the well pad. The yellow arrows illustrate the perimeter ditch and berm BMP that is being installed around the entire perimeter of location.

Inspection Photos  
Location Name: Blue Paintbrush /Pad  
Location ID: 460670



**Photo 2.** COGCC drone aerial imagery taken from location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: Blue Paintbrush /Pad  
Location ID: 460670



**Photo 3.** COGCC drone aerial imagery taken from location, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: Blue Paintbrush /Pad  
Location ID: 460670



**Photo 4.** COGCC drone aerial imagery taken from location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: Blue Paintbrush /Pad  
Location ID: 460670



**Photo 5.** Photo taken from the northwestern location, facing South. Photo illustrates a ditch and berm BMP that has been installed around the entire perimeter of location.



**Photo 6.** Photo taken from the northwestern location, facing East. See comments under Photo 5.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697503970