



## TANK BATTERY DECOMMISSIONING FORM

<b>SITE NAME:</b> Paradise V 16-22 O SA							<b>DATE:</b> 5/26/2022	<b>REM. PROJECT #:</b>	<b>WEATHER:</b> Sunny 80 degrees		
<b>SITE DIRECTIONS:</b> CR 22 and 19, W 0.1 and S 0.1 into							<b>CLIENT:</b> Oxy				
<b>LEGALS AND LAT/LONG:</b> 40.140842, -104.893206							<b>TASMAN PERSONNEL:</b> Sierra Kirylo				
<b>SOIL TYPES:</b> Well Graded Sand - SW							<b>SURFACE GRADIENT:</b> West				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)		1		
5/26/2022 14:00	AST-B01 @3"	55.4	Oxidization	No Odor	Yes	Lab	Buried or Partially Buried Vessel		1		
5/26/2022 14:02	AST-B02 @3"	17.5	No Staining	No Odor	Yes	N/A	Separator		1		
5/26/2022 14:10	SEP-B01 @3'	613.4	Organic Content	Slight HC Odor	Yes	Lab	Emission Control Device (ECD)		1		
5/26/2022 14:12	SEP-B02 @3'	3.7	Organic Content	No Odor	Yes	Lab	Dump Line		1		
5/26/2022 14:30	PW-B01 @4'	3.8	No Staining	No Odor	Yes	Lab	Wellhead				
5/26/2022 14:32	PW-N01 @3'	6.0	No Staining	No Odor	Yes	N/A	Flowline				
5/26/2022 14:34	PW-S01 @3'	0.9	No Staining	No Odor	Yes	N/A	Other:				
5/26/2022 14:36	PW-E01 @2'	10.6	Organic Content	No Odor	Yes	N/A	Soil Loads Removed				
5/26/2022 14:38	PW-W01 @3'	5.3	Organic Content	No Odor	Yes	N/A	IMPACTED SOIL IDENTIFIED?				
5/26/2022 14:50	PW-BG01 @2'	0.9	No Staining	No Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:				
5/26/2022 14:51	PW-BG01 @4'	1.5	No Staining	No Odor	Yes	Lab	Date	Number	CY		
5/26/2022 14:52	PW-BG02 @2'	1.1	Organic Content	No Odor	Yes	Lab					
5/26/2022 14:53	PW-BG02 @4'	0.2	Organic Content	No Odor	Yes	Lab					
5/26/2022 14:54	PW-BG03 @2'	0.4	No Staining	No Odor	Yes	Lab					
5/26/2022 14:55	PW-BG03 @4'	1.6	Organic Content	No Odor	Yes	Lab					
5/26/2022 15:10	MH-B01 @3"	0.4	No Staining	No Odor	Yes	N/A	Total Removed		0	0	
5/26/2022 15:15	ECD-B01 @3"	0.2	No Staining	No Odor	Yes	N/A	Disposal Facility:				
5/26/2022 15:20	DL-B01 @4'	8.7	No Staining	No Odor	Yes	N/A	Groundwater Recovery				
							DATE GW ENCOUNTERED:		DEPTH:		
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?				
							LNAPL OR SHEEN OBSERVED ON GW?				
GROUNDWATER SAMPLING							Date		BBLs		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
							Total Removed		0		
							Disposal Facility:				

**Photographic Log**

					
<b>Equipment ID:</b>		<b>Equipment Type:</b> Above Ground Storage Tank	<b>Equipment ID:</b>		<b>Equipment Type:</b>
<b>Material:</b> Steel	<b>Volume:</b> 300 BBL	<b>Contents:</b> Crude Oil	<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>
<b>Notes/Conditions:</b>			<b>Notes/Conditions:</b> Facing west		

**Photographic Log**

					
<b>Equipment ID:</b>		<b>Equipment Type:</b>	<b>Equipment ID:</b>		<b>Equipment Type:</b>
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>
<b>Notes/Conditions:</b> Facing north			<b>Notes/Conditions:</b> Facing south		

**Photographic Log**

 <p>PW-N01@3'</p>			 <p>PW-BG01@2' &amp; 4'</p>		
<b>Equipment ID:</b>		<b>Equipment Type:</b>	<b>Equipment ID:</b>		<b>Equipment Type:</b>
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>
<b>Notes/Conditions:</b> Facing north			<b>Notes/Conditions:</b> Background location to the north		

**Photographic Log**

					
<b>Equipment ID:</b>		<b>Equipment Type:</b>	<b>Equipment ID:</b>		<b>Equipment Type:</b>
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>
<b>Notes/Conditions:</b> Background location to the south			<b>Notes/Conditions:</b> Background location to the east		

**Photographic Log**

					
<b>Equipment ID:</b>		<b>Equipment Type:</b>	<b>Equipment ID:</b>		<b>Equipment Type:</b>
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>
<b>Notes/Conditions:</b> Facing north			<b>Notes/Conditions:</b> Facing north		

**Photographic Log**

					
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: Facing south			Notes/Conditions:		