

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/26/2022

Submitted Date:

05/27/2022

Document Number:

699603164

FIELD INSPECTION FORM

Loc ID 416234 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431079	WELL	PR	10/01/2020	OW	123-36403	SHABLE USX AB 11-65-1HNL	PR
431080	WELL	PR	10/01/2020	OW	123-36404	SHABLE USX AB 11-64-1HNL	PR
431860	WELL	PR	10/01/2020	OW	123-36824	DILLARD PC AB09-65-1HN	PR
431861	WELL	PR	10/01/2020	OW	123-36825	DILLARD PC AB09-64-1HN	PR

General Comment:

This is a WELL inspection.
Well(s): 4: Producing | PR.
Battery: Active.

Centralized Battery serves 1 Tank Battery Facility ID (481926).
Centralized Battery serves 3 Location IDs (wells). (416234, 431628, 450728).
(Well(s): 6: Producing | PR; 1: Plugged & Abandoned | PA; 1: Abandoned Location | AL).

Refer to Field Inspection Report doc. #699603162 and/or Facility ID #481926 for Battery / Facility, Equipment info.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	Methanol.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	4: Wellsites.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	4: Wellsites. Iron panel.		
Corrective Action:			Date:
Equipment:			
Type: Other	# 4		corrective date
Comment:	4: Wellsites. Gas lift injection lines.		
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:	4: Gas lift allocation meters. Calibration cards indicate calibration within last year. Last calibration: 05/18/2022. Active.		

Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	4: Wellsites.		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	4: Wellsites. Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	At Wellsite: 4: Methanol pumps, tanks w/ drip containment. Placards.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.587844,-104.525021
Comment:	Centralized Battery serves 1 Tank Battery Facility ID (481926). Centralized Battery serves 3 Location IDs (wells). (416234, 431628, 450728). Refer to Field Inspection Report doc. #699603162 and/or Facility ID #481926 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

BradenHead

Date of Last Brhd Test: 05/30/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 05/26/2022 at approximately 15:59 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: DILLARD PC /AB09-65-1HN Location ID: 416234 Well Name(s): Shable USX AB 11-65-1HNL, Shable USX AB 11-64-1HNL, Dillard PC AB09-65-1HN, Dillard PC AB09-64-1HN.</p> <p>API: 123-36403, 123-36404, 123-36824, 123-36825. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 4: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481926). Centralized Battery serves 3 Location IDs (wells). (416234, 431628, 450728). (Well(s): 6: Producing PR; 1: Plugged & Abandoned PA; 1: Abandoned Location AL).</p> <p>Refer to Field Inspection Report doc. #699603162 and/or Facility ID #481926 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/27/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699603165	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5765760