

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2022

Submitted Date:

05/28/2022

Document Number:

699603197

FIELD INSPECTION FORM

Loc ID 433191 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433201	WELL	AL	12/02/2015	LO	123-37531	Shable PC AB09-69-1HNL	RI
433206	WELL	AL	11/30/2015	LO	123-37535	Shable AB09-68-1HNL	RI
434974	WELL	AL	12/02/2015	LO	123-38395	Shable USX PC AB11-68-1HN	RI
434975	WELL	AL	12/02/2015	LO	123-38396	Shable Federal PC AB11-69-1HN	RI

General Comment:

This is a RECLAMATION | RI ; ABANDONED LOCATION inspection.
Well(s): 4: Abandoned Location | AL.
Location NEVER built.
No disturbance or evidence of oil & gas activity.

Inspected Facilities

Facility ID: 433201 Type: WELL API Number: 123-37531 Status: AL Insp. Status: RI

Facility ID: 433206 Type: WELL API Number: 123-37535 Status: AL Insp. Status: RI

Facility ID: 434974 Type: WELL API Number: 123-38395 Status: AL Insp. Status: RI

Facility ID: 434975 Type: WELL API Number: 123-38396 Status: AL Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: CRP

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built Pass

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: Location never built on existing Abandoned Location w/ NO active wells.
No disturbance or evidence of oil & gas activity.

Corrective Action: _____

Date _____

Overall Final Reclamation Pass Well Release on Active Location Multi-Well Location

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 05/25/2022 at approximately 15:15 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: Shable PC /AB09-69-1HNLPad Location ID: 433191 Well Name(s): Shable PC AB09-69-1HNL, Shable AB09-68-1HNL, Shable USX PC AB11-68-1HN, Shable Federal PC AB11-69-1HN. API: 123-37531, 123-37535, 123-38395, 123-38396. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 4: Abandoned Location AL.</p> <p>ABANDONED LOCATION Comment: 1.) Form 4 Sundry on file indicates Abandon Application for Permit-to-Drill (Form2). Well API Number 05-123-37531 has NOT been drilled. Date: 01/28/2016. Approved. Abandoned Location GPS coordinates: 40.593290 / -104.516420 2.) Form 4 Sundry on file indicates Abandon Application for Permit-to-Drill (Form2). Well API Number 05-123-37535 has NOT been drilled. Date: 01/28/2016. Approved. Abandoned Location GPS coordinates: 40.592980 / -104.516430 3.) Form 4 Sundry on file indicates Abandon Application for Permit-to-Drill (Form2). Well API Number 05-123-38395 has NOT been drilled. Date: 01/28/2016. Approved. Abandoned Location GPS coordinates: 40.492940 / -104.467720 4.) Form 4 Sundry on file indicates Abandon Application for Permit-to-Drill (Form2). Well API Number 05-123-38396 has NOT been drilled. Date: 01/28/2016. Approved. Abandoned Location GPS coordinates: 40.593190 / -104.516430</p> <p>Location NEVER built. No disturbance or evidence of oil & gas activity.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/28/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699603198	Site photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5765811