

Inspection Photos
Operator: Simcoe
API: 067-07136
Date: 5/27/2022



Photo 1. View of the project area from the well pad entrance facing center. .



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing within smooth brome, western wheatgrass, and sand dropseed.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with gambel oak, Indian ricegrass, antelope bitterbrush, black sagebrush, mat penstemon, and threadleaf sunflower.