

Inspection Photos
Operator: Simcoe
API: 067-09462
Date: 5/27/2022



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing within western wheatgrass and sand dropseed.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of reference area comprised of ponderosa pine forest with gambel oak, sandberg bluegrass, Oregon grape, and false goldenaster.