

Inspection Photos
Operator: Simcoe
API: 067-08678
Date: 5/27/2022



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing within the project area with blue grama, intermediate wheatgrass, western wheatgrass and sand dropseed.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of reference area comprised of ponderosa pine woodland with gambel oak, antelope bitterbrush, sandberb bluegrass, and mules ears in the understory.