

**Inspection Photos**  
**Location Name: Clementine B. Coburn B unit 1**  
**Location ID: 318481**



**Photo 1 WH sign.**

**Photo 2 WH**

**Inspection Photos**  
**Location Name: Clementine B. Coburn B unit 1**  
**Location ID: 318481**



**Photo 3 PJ.**

**Photo 4 Ancillary equip.**

**Inspection Photos**  
**Location Name: Clementine B. Coburn B unit 1**  
**Location ID: 318481**



**Photo 5 TB sign.**

**Photo 6 TB.**

**Inspection Photos**  
**Location Name: Clementine B. Coburn B unit 1**  
**Location ID: 318481**



**Photo 7 Gas Meter Run x 3, cards indicate that calibration is not current.**

**Photo 8 HHS.**