

Inspection Photos
Location Name: Hunt 8-60-6C PAD
Location ID: 454166




Photo 1 – Day Tank Netting in disrepair and debris inside Containment



Photo 2 – Separators

Inspection Photos
Location Name: Hunt 8-60-6C PAD
Location ID: 454166



Photo 3 – Tank Battery



Photo 4 – Tank Battery Sign



Inspection Photos
Location Name: Hunt 8-60-6C PAD
Location ID: 454166



Photo 5 – Wildlife Netting in is disrepair



Photo 6 – Oily Waste NOT Covered – Properly Remove from Location

Inspection Photos
Location Name: Hunt 8-60-6C PAD
Location ID: 454166



Photo 7 – Wildlife Netting in is disrepair




Photo 8 – Stained Soil at Back Pressure Regulator

Inspection Photos
Location Name: Hunt 8-60-6C PAD
Location ID: 454166



Photo 9 – Wildlife Netting in is disrepair



Photo 10 – ECD

Inspection Photos
Location Name: Hunt 8-60-6C PAD
Location ID: 454166




Photo 11 – Unmarked Risers




Photo 12 – Unmarked Risers



Inspection Photos
Location Name: Hunt 8-60-6C PAD
Location ID: 454166



Photo 13 – 5-10 Wellhead



Photo 14 – 5-6 Wellhead



Inspection Photos
Location Name: Hunt 8-60-6C PAD
Location ID: 454166



Photo 15 – New Wells – Surface Spud