

Inspection Photos
Location Name: State of Colorado C 5
Location ID: 320395



Photo #1 Location Sign illegible.

Photo #2 Tanks.

Inspection Photos
Location Name: State of Colorado C 5
Location ID: 320395




Photo #3 Separator & ECD.

Photo #4 No wild life protection.

Inspection Photos
Location Name: State of Colorado C 5
Location ID: 320395



Photo #5 Pump Jack.



Photo #6 plastic buckets being stored in the base of the pump jack.

Inspection Photos
Location Name: State of Colorado C 5
Location ID: 320395



Photo #7 Safety guards not present.

Photo #8 Safety guards not present, no containment on chemical tank and well sign illegible.

Inspection Photos
Location Name: State of Colorado C 5
Location ID: 320395




Photo #9 Stained soil under pump jack motor.